



Service Bulletin

Unit model: L X E 10D, 10E

Compressor Explosion accident (圧縮機爆発事故について)

To whom it may concern:

We would like to draw your attention to the recent incidents affecting marine container refrigeration units of several manufacturers.

A few cases of reefer compressors explosion have been reported this year by certain shipping line. Also it is reported that subjected reefers has experienced refrigeration system works in Vietnam.

While Daikin has never experienced any compressor explosion of refrigeration units to date, the cause of the explosions has not been identified yet and there may be still a big risk of serious injuries.

Daikin is monitoring the case very closely, but until we fix the details of the safety bulletin, we strongly recommend that you put your own safety on a very first priority and pay extra caution in case you need to repair container refrigeration units.

[Japanese]

[関係各位]

最近 同業他社で発生しました、コンテナ冷凍機の事故についてPRさせていただきます。

本年、他社製 コンテナ冷凍機で圧縮機の破裂事故が数件発生しているという情報を船社様より入手しております。 該当機はベトナムに於いて冷媒系統の修理作業を実施していたとの事です。

ダイキンのコンテナ冷凍機圧縮機では破裂事故は発生しておりませんが、重大な人身事故になりますので、ダイキンとしても本件について注目しております。また、事故原因がはっきりしていないため、具体的な注意内容をお知らせする事は出来ませんが、ユニットの整備作業を実施される場合は、十分安全に注意して作業される様、よろしくお願ひいたします。